

URGENT

*TB 1-2840-241-20-20

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

INSPECTION FOR AND REMOVAL OF THE PY ACCUMULATOR, OH-58A/C

Headquarters, Department of the Army, Washington, D. C.
28 July 2000

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE UNTIL RESCINDED OR
SUPERSEDED.

1. Priority Classification. URGENT.

NOTE

IAW AR 95-1, paragraph 6-6.a., MACOM Commanders may authorize temporary exception from SOF message requirements. Exceptions may only occur when combat operations or matter of life or death in civil disasters or other emergencies are so urgent that they override the consequences of continued aircraft operations.

a. Aircraft in Use. Upon receipt of the message/TB (whichever occurs first), make the following entry on the DA Form 2408-13-1. Enter a **Red Horizontal Dash //--//** status symbol with the following statement: "Inspect for installation of the Power Turbine Governor PY Accumulator IAW OH-58-00-ASAM-06 (TB 1-2840-241-20-20) within the next 10 flight hours, but NLT 10 July 2000". Clear the **Red Horizontal Dash //--//** entry when the procedures IAW paragraphs 8 and 9 are completed. The affected aircraft shall be inspected as soon as practical but NLT 10 July 2000. Commanders who are unable to comply with the requirements of subject message/TB within the time frame specified will upgrade the affected aircraft status symbol to a **Red //X//**.

b. Aircraft in Depot Maintenance. Same as paragraph 1.a.

c. Aircraft Undergoing Maintenance. Same as paragraph 1.a.

d. Aircraft in Transit. Same as paragraph 1.a.

*This TB supersedes USAAMCOM Safety of Flight (SOF) Messages, OH-58-00-ASAM-06 (261138Z Jun 00).