

URGENT

***TB 1-2840-241-20-21**

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

FOR ALL OH-58A/C AND H-6 AIRCRAFT WITH T63-A-720 OR 250-C20B ENGINES INSTALLED, ONE TIME INSPECTION OF PRESSURE PROBE ELBOW

Headquarters, Department of the Army, Washington, D. C.
24 September 2001

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE UNTIL RESCINDED OR
SUPERSEDED.

1. Priority Classification. URGENT.

NOTE

IAW AR 95-1, paragraph 6-6a, MACOM commanders may authorize temporary exception from ASAM message/TB requirements. Exception may only occur when combat operations or matter of life or death in civil disasters or other emergencies are so urgent that they override the consequences of continued aircraft operation.

a. Aircraft in Use. Upon receipt of the subject message/TB, make the following entry on the DA Form 2408-13-1. Enter a **Red Horizontal Dash //--//** status symbol with the following statement: "Inspect Pressure Probe Elbow IAW OH-58-01-ASAM-04 (TB 1-2840-241-20-21) within the next 100 flight hours, but NLT 28 December 2001." Clear the **Red Horizontal Dash //--//** entry when the procedures IAW para 8 and 9 are completed. The affected aircraft shall be inspected as soon as practical, but no later than 28 Dec 2001. Commanders who are unable to comply with the requirements of the subject message/TB within the time frame specifies will upgrade the affected aircraft status symbol to a **Red X**.

b. Aircraft in Maintenance Facility.

(1) Aircraft in AVUM, AVIM or Depot. Commanders and facility managers will not issue aircraft until they are in compliance with this message.

(2) Aircraft at Contractor Facility. N/A.

c. Aircraft in Transit.

(1) Surface/Air Shipment. Same as paragraph 1.a.

***This TB supersedes USAAMCOM Aviation Safety Action Message (ASAM), 121945Z, JUL 01, OH-58-01-ASAM-04.**