

URGENT

TB 1-2840-263-01

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

ONE TIME INSPECTION AND RECURRING INSPECTION OF NEW SELF SEALING MAGNETIC CHIP DETECTORS OH-58D(R) HELICOPTER ENGINES

Headquarters, Department of the Army, Washington, D. C.
4 May 2000

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE
UNTIL RESCINDED OR SUPERSEDED.

1. Priority Classification. URGENT

a. Aircraft in Use. Upon receipt of this Technical Bulletin (TB) the condition status symbol of the cited aircraft will be changed to a red horizontal dash. The red horizontal dash entry shall state "Inspect magnetic plug (chip detectors) TB 1-2840-263-01 at the next scheduled 20 hour engine inspection and subsequent 20 hour scheduled inspection." The red horizontal dash may be cleared when the inspection criteria in paragraph 8 and corrective actions in paragraph 9 are completed. The affected aircraft shall be inspected as soon as practical but no later than the next 20 hour engine inspection. Failure to comply with the requirements of this TB within the time frame will cause the status symbol to be upgraded to a red X.

b. Aircraft in Depot Maintenance. Same as paragraph 1. a.

c. Aircraft Undergoing Maintenance. Same as paragraph 1. a.

d. Aircraft in Transit. Same as paragraph 1. a.

e. Maintenance Trainers (Category A and B). Not applicable.

f. Component/Parts in Stock Including War Reserves at All Levels (Depot and Others). Not Applicable.

2. Task/Inspection Suspense Date. At the next scheduled 20 hour engine inspection and report in accordance with paragraph 14. b.

3. Reporting Compliance Suspense Date. Report compliance in accordance with paragraph 14. a. no later than 4 May 2000.