URGENT

***TB 1–2840–241–20–22**

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

INSPECTION OF FIRST STAGE NOZZLE SHIELD ALL T63–A–720 ENGINES ON OH–58A/C AIRCRAFT

Headquarters, Department of the Army, Washington, D. C.
18 January 2002

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE UNTIL RESCINDED OR SUPERSEDED.

1. Priority Classification. Urgent.

a. Aircraft in Use. Upon receipt of this Technical Bulletin (TB) make the following entry on DA Form 2408–13–1: Enter a Red Horizontal Dash //–// status symbol with the following statement: Inspect T63–A–720 engine in accordance with this TB. Clear Red Horizontal Dash //–// entry when the procedures in paragraphs 8 and 9 are completed. Affected aircraft shall be inspected as soon as practical but no later than 28 December 2001. Commanders who are unable to comply with requirements of this TB within time frame specified will upgrade affected aircraft status to a Red //X//.

b. Aircraft in Maintenance Facility:

(1) Aircraft in AVUM, AVIM, or Depot. Commanders and Facility Managers will not issue aircraft until they are in compliance with this TB.

(2) Aircraft at Contractor Facility. Bell Special Operations Force Support activity will inspect DD 250 aircraft prior to those aircraft departing for ferry to final destination.

c. Aircraft in Transit.

(1) Surface/Air Shipment. Same as paragraph 1. a.

(2) Ferry Status.

(a) Same as paragraph 1. a.

(b) Bell or Special Operations Forces Support activity will inspect DD 250 aircraft prior to those aircraft departing for ferry to final destination.

d. Maintenance Trainers (Category A and B). Same as paragraph 1. a.

e. Component/Parts in Stock Including War Reserves at All Levels (Depot and Others). Upon receipt of this TB, Depot and Materiel Activity Activity Commanders will ensure materiel condition tags of all items in all condition codes listed in paragraphs 6 and 7 are annotated to read TB 1–2840–241–20–22 , Inspection of First Stage Nozzle Shields, not complied with.

*This TB supersedes OH–58–02–ASAM–03 132125Z Dec. 01