URGENT

***TB 1-2840-248-30-1**

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

T700 SERIES ENGINE RESET PROGRAM

Headquarters, Department of the Army, Washington, D. C.
08 December 2003

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE UNTIL RESCINDED OR SUPERSEDED.

1. **Purpose.** This bulletin is to be used as guidance for the restoration of performance to T700 engines that have been operating in Southwest Asia (SWA). These engines are susceptible to damage and accelerated performance degradation because of their exposure to the hostile sand and dirt environment of SWA.

2. **Priority Classification.** This technical bulletin is classified as **URGENT**. Equipment in use (including Equipment in Supply or Maintenance Activities below Depot Level and Equipment in Administrative Storage) will be inspected as soon as practical.

3. **End Items to be Inspected.**

NOMENCLATURE	PART NUMBER	NSN
T700-GE-700	6035T00G01	2840-01-070-1003
T700-GE-701	6044T06G01	2840-01-114-2211
T700-GE-701C	6071T24G01	2840-01-284-4011

4. **Modules (Components, Assemblies, and Subassemblies) to be inspected.** As required.

5. **Parts to be inspected.** Not applicable.

6. **Application.**

a. Level of Maintenance. Aviation Unit Maintenance (AVUM)/Aviation Intermediate Maintenance (AVIM).

b. Applied by. AVUM/AVIM.

(1) Maximum Power Check – Operator.

(2) Cleaning of Engine and Engine Components – AVUM.

*This TB supersedes TB 1-2840-248-30-1 dated 22 August 2003.