*TB 9-4931-363-50

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

CALIBRATION PROCEDURE FOR FIRE CONTROL SUBSYSTEM TEST SET AN/GSM-249 4931-00-121-8707

Headquarters, Department of the Army, Washington, DC
1 April 1976

REPORTING OF ERRORS

You can help improve this publication by calling attention to errors and by recommending improvements and stating your reasons for the recommendations. Your letter or DA Form 2028, Recommended Changes to Publications, should be mailed directly to Commander, U.S. Army Aviation and Missile Command, ATTN: AMSAM-TMD-EP, Redstone Arsenal, A1 35898-5000. FAX to DSN 788-2313 (commercial 256-842-2313). A reply will be furnished directly to you.

			Paragraph	Page
SECTION	I.	IDENTIFICATION AND DESCRIPTION		
		Test instrument identification	1	2
		Calibration Description	2	3
		Forms and Records	3	3
	II.	EQUIPMENT REQUIREMENTS		
		Equipment and Accessories Required	4	3
	III.	PRELIMINARY OPERATIONS		
		Preliminary Operation	5	4
	IV.	CALIBRATION PROCESS		
		Digital Multimeter Voltage And Accuracy	6	5
		DC Performance Check		5
		AC Performance Check		6
		Resistance Performance Check		6
		Calibration Adjustments		6
		Final Procedure	7	7

*This bulletin supersedes TB 4931-363-34, 1 June 1975

SECTION I
IDENTIFICATION AND DESCRIPTION

WARNING

The digital multimeter of the test set contains high-voltage converters. Removal of high voltage levels is not assured until the multimeter is disconnected and high-voltage points are grounded. Use insulated calibration tool when required. High voltage may be present at adjustment points. Dangerous voltages and currents are present in voltage calibration equipment.

1. Test Instrument Identification. This bulletin provides information for the periodic calibration of Fire Control Subsystem Test Set AN/GSM-249. The component of this test set requiring calibration is the digital multimeter (fig. 1).



Figure 1. Fire control subsystem test set - control panel