TECHNICAL BULLETIN



INSTALLATION INSTRUCTIONS FOR INSTALLATION KIT, ELECTRONIC EQUIPMENT MK-2867/VRC (NSN 5895-01-442-4584) (EIC: N/A)

TO PERMIT INSTALLATION OF MULTIPLEXER, FREQUENCY HOPPING TD-1456/VRC

IN

SINCGARS-EQUIPPED VEHICLE (GENERIC)

Approved for public release; distribution is unlimited.

HEADQUARTERS, DEPARTMENT OF THE ARMY
1 JANUARY 2004

Technical Bulletin
No. 11-5820-890-20-112

HEADQUARTERS,
DEPARTMENT OF THE ARMY
Washington, D.C., 1 January 2004

INSTALLATION INSTRUCTIONS FOR INSTALLATION KIT, ELECTRONIC EQUIPMENT MK-2867/VRC (NSN 5895-01-442-4584) (EIC: N/A) TO PERMIT INSTALLATION OF MULTIPLEXER, FREQUENCY HOPPING TD-1456/VRC IN SINCGARS-EQUIPPED VEHICLES (GENERIC)

REPORTING OF ERRORS AND RECOMMENDING IMPROVEMENTS

You can help improve this manual. If you find any mistakes or if you know of a way to improve the procedures, please let us know. Mail your letter or DA Form 2028 (Recommended Changes to Publications and Blank Forms) direct to: Commander, US Army Communications-Electronics Command Fort Monmouth, ATTN: AMSEL-LC-LEO-D-CS-CFO, Fort Monmouth, NJ 07703-5006. The Fax number is 732-532-1413, DSN 992-1413. You may also e-mail your recommendation to: AMSEL-LC-LEO-PUBS-CHG@ cecom3.monmouth.army.mil

In either case, a reply will be furnished direct to you.

TABLE OF CONTENTS

Subject	Section	Page
General Information	0.	1
Purpose of Installation	1.	3
End Item or System to be Modified	2.	3
Application Times	3.	3
Time for Completion of Installation	3.1	3
Time for Installation of One Assembly or Component	3.2	3
Preparation for Installation	4.	3
Preparation of Work Area	4.1	3
Preparation of Vehicle	4.2	3
Preparation of Installation Kit	4.3	3
Contents of Installation Kit	4.4	4
Consumable Materials Required	4.5	6
Tools and Test, Measurement, and Diagnostic Equipment (TMDE) Required	4.6	6
Installation Procedures	5.	7
Installation of Antenna, Vehicular, AS-3900A/VRC (antenna)	5.1	7
Installation of Antenna Mounting Base	5.1.1	7
Installation of Top Antenna Assembly	5.1.2	10
Installation of Mounting Base, Electrical Equipment MT-6845/VRC (mounting base)	5.2	11
Installation of Cables	5.3	13
Post-Installation and Checkout	5.4	14
Appendix A References		A-1

LIST OF ILLUSTRATIONS

Figure	Title	Page
4-1	MK-2867/VRC Illustrated Parts List	5
5-1 (1)	Antenna Base Installation: Antenna Port	8
5-1 (2)	Antenna Base Installation: Antenna Bracket	9
5-2	Top Antenna Assembly Installation	10
5-3	Mounting Base Installation	12
5-4	Cable Diagram – For TD-1456/VRC	15

LIST OF TABLES

Table	Title	Page
3-1	Installation Times	3
4-1	Parts List for Installation Kit, Electronic Equipment MK-2867/VRC	4
4.2	Consumable Materials Required	6
4.3	Tools and Test, Measurement, and Diagnostic Equipment (TMDE) Required	6

0. GENERAL INFORMATION.

0.1 SCOPE.

This technical bulletin (TB) provides installation instructions for Installation Kit, Electronic Equipment MK-2867/VRC, commonly referred to as the Mounting Kit (MK).

The MK is used for installation of Frequency Hopping Multiplexer TD-1456/VRC at field locations. The information contained in this technical bulletin is the official authorization to perform the installation at the unit maintenance level.

NOTE

This TB is not an authorization for requisition or turn-in of vehicles or SINCGARS radio sets. This TB does not establish quantity or types of vehicles or radios assigned to units.

0.2 CONSOLIDATED INDEX OF ARMY PUBLICATIONS AND BLANK FORMS.

Refer to the latest issue of DA Pam 25-30 to determine whether there are new editions, changes, or additional publications pertaining to the equipment.

0.3 MAINTENANCE FORMS, RECORDS, AND REPORTS.

0.3.1 Reports of Maintenance and Unsatisfactory Equipment. Department of the Army forms and procedures used for equipment maintenance will be those prescribed by DA Pam 738-750, as contained in Maintenance Management Update. Air Force personnel will use AFR 66-1 for maintenance reporting and TO-00-35D54 for unsatisfactory equipment reporting. Navy personnel will report maintenance performed utilizing the Maintenance Data Collection Subsystem (MDCS) IAW OPNAVINST 4790.2, Vol 3 and unsatisfactory material/conditions (UR) IAW OPNAVINST 4790..2, Vol 2, chapter 17. Marine Corps maintains forms and procedures as prescribed by TM 4700-15/1.

0.3.2 Reporting of Item and Packaging Discrepancies. Fill out and forward SF 364 (Supply Discrepancy Report (SDR)) as prescribed in AR 735-11-2/DLAR 4140.55/SECNAVINST 4355.18/AFR 400-54/MCO 4430.3J.

0.3.3 Transportation Discrepancy Report (TDR) (SF 361). Fill out and forward Transportation Discrepancy Report (TDR) (SF 361) as prescribed in AR 55-38/NAVSUPINST 4610.33C/AFR 75-18/MCO P4610.19D/DLAR 4500.15.

0.4 DESTRUCTION OF ARMY ELECTRONICS MATERIEL.

Destruction of Army electronics materiel to prevent enemy use shall be in accordance with TM 750-244-2.

0.5 REPORTING EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR).

0.5.1 Army. If your equipment needs improvement, let us know. Send us an EIR. You, the user, are the only one who can tell us what you don't like about your equipment. Let us know why you don't like the design or performance. Put it on an SF 368 (Product Quality Deficiency Report). Mail it to: Commander, US Army Communications-Electronics Command and Fort Monmouth, ATTN: AMSEL-LC-LEO-D-CS-CFO, Fort Monmouth, New Jersey 07703-5006. We'll send you a reply.

0.5.2 Air Force. Air Force personnel are encouraged to submit EIR's in accordance with AFR 900-4.

0.5.3 Navy. Navy personnel are encouraged to submit EIR's through their local Beneficial Suggestion Program.

0.5.4 Marine Corps. QDR shall be reported on SF 368 in accordance with MCO P4855.10, Product Quality Deficiency Report Manual. Submit to Commanding General, Marine Corps Logistics Base (Code 850), Albany, Georgia 31704-5000.