

URGENT

*TB 1-2840-241-20-17

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

MANDATORY INSPECTION AND REPLACEMENT OF THE FUEL CONTROL, FOR ALL OH-58A/C SERIES AIRCRAFT

Headquarters, Department of the Army, Washington, D. C.
1 June 1999

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE UNTIL RESCINDED OR
SUPERSEDED.

1. Priority Classification. URGENT.

NOTE

See AR 95-1, paragraph 6-6.a., for noncompliance authority of major
commanders.

a. Aircraft in Use. Upon receipt of this TB, the condition status symbol of the cited aircraft will be changed to a **Red Horizontal Dash -**. The **Red Horizontal Dash -** entry shall state "Complete the inspection procedures in paragraph 8 of this TB prior to next flight". The **Red Horizontal Dash -** may be cleared when the inspection of paragraph 8 is completed. The affected aircraft shall be inspected as soon as practical, but no later than the task/inspection suspense date. Failure to comply with the requirements of this TB within the time frame will cause the status symbol to be upgraded to a **Red X**.

b. Aircraft in Depot Maintenance. N/A.

c. Aircraft Undergoing Maintenance. Same as paragraph 1.a.

d. Aircraft in Transit.

(1) Surface/Air Shipment. Same as paragraph 1.a.

(2) Ferry Status. Same as paragraph 1.a.

e. Maintenance Trainers (Category A and B). Same as paragraph 1.a.

*This TB supersedes USAAMCOM Safety of Flight (SOF) Message, 171323Z, MAY 99
OH-58-99-ASAM-06.