

URGENT

*TB 1-2840-241-20-18

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

MANDATORY ONE TIME AND RECURRING INSPECTION OF THE PC FILTER TUBE ASSEMBLY, FOR ALL OH-58A/C SERIES AIRCRAFT

Headquarters, Department of the Army, Washington, D. C.
7 April 1999

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE UNTIL RESCINDED OR
SUPERSEDED.

NOTE

Safety of Flight (SOF) Message 171230Z, gives the wrong TB number of
TB 55-1520-220-18. The correct number is the number of this TB.

1. **Priority Classification.** URGENT.

NOTE

See AR 95-1, paragraph 6-6.a., for noncompliance authority of major
commanders.

a. **Aircraft in Use.** Upon receipt of this TB, the condition status symbol of the cited aircraft will be changed to a **Red Horizontal Dash -**. The **Red Horizontal Dash -** may be cleared when the requirements of paragraph 8. and the correction procedures described in paragraph 9. are completed. The affected aircraft shall be inspected as soon as practical, but no later than the task/inspection suspense date. Failure to comply with the requirements of this TB within the time frame will cause the status symbol to be upgraded to a **Red X**.

b, **Aircraft In Depot Maintenance.** Aircraft will not be issued until compliance with this TB has been completed.

c. **Aircraft Undergoing Maintenance.** Same as paragraph 1 .a.

*This TB supersedes USAAMCOM Safety of Flight (SOF) Message, 171230Z, MAR 99
OH-58-99-ASAM-03.