

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

INSPECTION AND REPAIR FOR T55 SERIES ENGINE RESET PROGRAM (T55-L-712 AND T55-GA-714A)

Headquarters, Department of the Army, Washington, D. C.
30 January 2004

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

NOTE

THIS PUBLICATION IS EFFECTIVE UNTIL RESCINDED OR SUPERSEDED.

- 1. Purpose.** This bulletin is to be used as guidance for the restoration of performance to T55 engines that have been operating in Southwest Asia (SWA). These engines are susceptible to damage and accelerated performance degradation because of their exposure to the hostile sand and dirt environment of SWA.
- 2. Priority Classification.** This technical bulletin is classified as ROUTINE. Equipment in use (including Equipment in Supply or Maintenance Activities below Depot Level and Equipment in Administrative Storage) will be inspected as soon as practical.
- 3. End Items to be Inspected.**

NOMENCLATURE	PART NUMBER	NATIONAL STOCK NUMBER
T55-L-712	2-001-020-23	2840-01-030-4890
T55-GA-714A	2-001-020-39	2840-01-458-5361

- 4. Modules** (Components, Assemblies, and Subassemblies) to be inspected. Not applicable.
- 5. Parts to be Inspected.** As indicated in paragraph 7 below.
- 6. Application.**
 - a. Level of Maintenance. Aviation Unit Maintenance (AVUM)/Aviation Intermediate Maintenance (AVIM).
 - b. AVUM/AVIM tasks are as follows: