

SB 11-569

DEPARTMENT OF THE ARMY SUPPLY BULLETIN

REPLACEMENT AND DISPOSITION OF CABLE ASSEMBLIES, TELEPHONE CX-4566/G AND CX-4760/U CONTAINING UNSUITABLE CONTACT ASSEMBLIES

Headquarters, Department of the Army, Washington, D.C.
12 December 1963

1. **Purpose.** a. To authorize the replacement of Cable Assemblies CX-4566/G and CX-4760/U which contain unsuitable contact assemblies.

b. To provide for disposition of the replaced cable assemblies.

2. **Information.** a. *General.* Contact assemblies in Connectors U-185()/U received from early production are considered unsuitable when rated with the standard Contact Assembly MX-3227/G, FSN 5935-823-3262. The mating of different versions of the contact assemblies results in damage to the MX-3227/G. MWO 11-5935-205-35/1 replaces unsuitable contact assemblies with standard Contact Assemblies MX-3227/G in Connectors U-186()/U and U-187()/U, when installed in Army Area Communication System equipment.

b. *Identification of cable assemblies to be Replaced.* Cable assemblies to be replaced can be readily identified by examining the contact assembly in each connector U-185()/U. The *suitable* or *standard* contact assemblies will have the type number MX-3227/U molded on the exposed edge of the plastic portion of the Assembly. Any contact assemblies bearing other or no identification markings are considered to be *unsuitable*. Those cable assemblies listed in table I are to be replaced. See the tables at the end of this bulletin for proper

nomenclature and FSN to be applied to the cable assemblies following positive identification.

c. *Replacement Program Controls.* To provide adequate controls to the cable assembly replacement program, overseas and CONUS Commands will not submit requisitions for replacement Cable Assemblies CX-4566/G and CX-4760/U until requested by the U.S. Army Electronics Materiel Agency.

3. **Procedure.** a. Upon receipt of this supply bulletin, all Cable Assemblies CX-4566()/G and CX-4760()/U will be physically inspected, identified, and classified in accordance with the information contained in paragraph 2 and in tables I through III.

b. Property books and/or stock records will be adjusted to reflect the changes as appropriate.

c. Upon receipt of authorization to requisition, overseas and CONUS Commands will submit requisitions through normal channels to the Commanding General, U.S. Army Electronics Materiel Agency, ATTN: SELMA-F3a1, 225 South Eighteenth Street, Philadelphia, Pa. 19103, citing this bulletin and the original Basis or Issue as authority.

d. Replaced cable assemblies will be reported to the appropriate mission depot for disposition in accordance with existing regulations.

THIS PUBLICATION IS A COURTESY QUICK COPY FROM THE UNITED STATES ARMY PUBLICATIONS DISTRIBUTION CENTER, ST. LOUIS, MISSOURI, TO MEET YOUR NEEDS WHILE WE REPLENISH OUR REGULAR STOCK.