

***TB 9-4931-503-35**

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

CALIBRATION PROCEDURE FOR DELAYING TIME BASE, TEKTRONIX, TYPE 5B42; TIME BASE, TEKTRONIX, TYPE 5B40; AND DUAL-TRACE AMPLIFIER, TEKTRONIX, TYPE 5A48

Headquarters, Department of the Army, Washington, DC
25 February 2003

Approved for public release; distribution is unlimited

REPORTING OF ERRORS AND RECOMMENDING IMPROVEMENTS

You can improve this manual. If you find any mistakes or if you know of a way to improve these procedures, please let us know. Mail your letter, DA Form 2028 (Recommended Changes to Publications and Blank Forms) directly to Commander, U.S. Army Aviation and Missile Command, ATTN: AMSAM-MMC-MA-NP, Redstone Arsenal, AL 35898-5000. A reply will be furnished to you. You may also provide DA Form 2028 information to AMCOM via e-mail, fax, or the World Wide Web. Our FAX number is: DSN 788-6546 or Commercial 256-842-6546. Our e-mail address is: 2028@redstone.army.mil. Instructions for sending an electronic 2028 may be found at the back of this manual. For the World Wide Web, use: <https://amcom2028.redstone.army.mil>.

		Paragraph	Page
SECTION	I.	IDENTIFICATION AND DESCRIPTION	
		Test instrument identification	1 2
		Forms, records, and reports	2 2
		Calibration description	3 2
	II.	EQUIPMENT REQUIREMENTS	
		Equipment required	4 4
		Accessories required	5 4
	III.	CALIBRATION PROCESS FOR DELAYING TIME BASE, TEKTRONIX, TYPE 5B42	
		Preliminary instructions	6 4
		Equipment setup	7 5
		External horizontal input and main sweep timing	8 6
		Delayed sweep and delay time/differential time measurement	9 10
		Final procedure	10 12

*This bulletin supersedes TB 9-4931-503-35, 19 March 1993.

	Paragraph	Page
IV. CALIBRATION PROCESS FOR TIME BASE, TEKTRONIX, TYPE 5B40		
Preliminary instructions	11	12
Equipment setup.....	12	13
External horizontal input	13	14
Horizontal time accuracy	14	14
Final procedure.....	15	17
V. CALIBRATION PROCESS FOR DUAL- TRACE AMPLIFIER, TEKTRONIX, TYPE 5A48		
Preliminary instructions	16	17
Equipment setup.....	17	17
External horizontal input	18	18
Aberrations and risetime.....	19	21
Final procedure.....	20	22

SECTION I IDENTIFICATION AND DESCRIPTION

1. Test Instrument Identification. This procedure provides instructions for the calibration of Delaying Time Base, Tektronix, Type 5B42; Time Base, Tektronix, Type 5B40; and Dual-Trace Amplifier, Tektronix, Type 5A48. The manufacturer's manuals were used as the prime data sources in compiling these instructions. The equipment being calibrated will be referred to as the TI (test instrument) throughout this bulletin.

a. Model Variations. Variations among models are described in text.

b. Time and Technique. The time required for this calibration is approximately 2 hours, using the dc and low frequency technique.

2. Forms, Records, and Reports

a. Forms, records, and reports required for calibration personnel at all levels are prescribed by TB 750-25.

b. Adjustments to be reported are designated (R) at the end of the sentence in which they appear. When adjustments are in tables, the (R) follows the designated adjustment. Report only those adjustments made and designated with (R).

3. Calibration Description. TI parameters and performance specifications which pertain to this calibration are listed in table 1.